

AGA ENVIRONMENTAL, INC.

July 11, 2016

US Environmental Protection Agency – Region 2
Division of Enforcement * Compliance Assistance
Air Compliance Branch (DECA-ACB)
290 Broadway – 21st Fl, New York, NY 10007-1866

Attn: Max Rehfeld

Re: Lehman College – Gillet Hall
2920 Goulden Avenue
Bronx, New York
DASNY Project No. 303280
Façade Restoration

Dear Mr. Rehfeld:

Please be advised that the above referenced, which was previously postponed, has a new starting date of July 25, 2016. The end date is December 31, 2016.


Also, please note the following change:

VII. Approximate amount of asbestos
Please change from 75 SF to 355 SF

Attach please find the notification referred to with the appropriate changes.

If you have any questions or need additional information in reference to this project do not hesitate to call my office.

Very truly yours,



Gilberto Padilla
President

23 Sheer Plaza, Plainview, New York 11803 * Tel (516) 420-0001/0003 * Fax (516) 420-0007
gilbert@agaenvironmental.com

NOTIFICATION OF DEMOLITION AND RENOVATION

Operator Project #	Postmark	Date Received	Notification#		
I. Type of Notification (O = Original R = Revised C = Cancelled) O					
II. FACILITY INFORMATION (identify owner, removal, contractor, and other operator)					
OWNER NAME: DORMITORY AUTHORITY STATE OF NY					
Address: ONE PENN PLAZA					
City: NEW YORK	State: NY	Zip: 10119			
Contact: PAULINA BARTUAL	Tel: (718) 960-7185				
REMOVAL CONTRACTOR: AGA ENVIRONMENTAL					
Address: 23 SHEER PLAZA					
City: PLAINVIEW	State: NY	Zip: 11803			
Contact: GILBERTO PADILLA	Tel: (516) 420-0001				
III. TYPE OF OPERATION (D=Demo O=Ordered Demo R=RENOVATION E=EMER Renovation) Asbestos Removal					
IV. IS ASBESTOS PRESENT? (Yes/No) Yes					
V. FACILITY DESCRIPTION (include building name, number and floor or room number)					
Bldg. Name: LEHMAN COLLEGE - GILLET HALL					
Address: 2920 GOULDEN AVENUE					
City: BRONX	State: NY - 10468	County: BRONX			
Site Location: FACADE					
Building Size:	# of Floor: --	Age in Years:			
Present Use: COLLEGE	Prior Use:				
VI. PROCEDURE, INCLUDING ANALYTICAL METHOD, IF APPROPRIATE, USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: MATERIAL: BULK SAMPLING					
VII. APPROXIMATE AMOUNT OF ASBESTOS INCLUDING:					
1. Regulated ACM to be Removed 2. Category I ACM Not Removed 3. Category II ACM Not Removed	RACM To Be Removed	Non-friable Asbestos Material Not To Be Removed		Indicate Unit of Measurement Below	
		Category I	Category II	UNIT	
				Ln Ft:	Ln M:
Surface Area - CAULKING (DRIP EDGES, DOOR, WINDOWS, LOUVERS), FLASHING & WATERPROOFING				Sq. Ft: 355	Sq M:
OTHER				Cu Ft:	Cu M:
VIII. SCHEDULE DATES ASBESTOS REMOVAL (MM/DD/YY)					
Start: 7/25/16		Complete: 12/31/16			
IX. SCHEDULE DATES DEMO/RENOVATION (MM/DD/YY) start:					
Complete:					